

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2011 Levee Inspection Results**

**Reclamation District No. 0784 Plumas Lake**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 0784 Plumas Lake**

Waterway			Bank	Unit Miles
Unit No. 01 Yuba River			Left	2.22

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/17/2011 - 3/17/2011			
DWR Inspector	Clay Thomas			
Accompanied By	Steve Fordice RD-784			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.22	03/17/2011 03/17/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.04	2.21	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	39.134426 ° -121.552686 °	39.125935 ° -121.588624 °	2
2	0.04	2.21	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	39.134426 ° -121.552686 °	39.125934 ° -121.588624 °	1
3	1.68	1.68	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	39.129852 ° -121.581830 °	39.129852 ° -121.581830 °	5 Y
4	1.68	1.68	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	39.129852 ° -121.581830 °	39.129852 ° -121.581830 °	6 Y
5	1.79	1.87	Earthen Levee	Encroachments	LS	PO	Landscaping	39.129849 ° -121.583793 °	39.129858 ° -121.585183 °	4

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.22	03/17/2011 03/17/2011	Clay Thomas

Levee Mile Report Line	3
Start Levee Mile	1.68
End Levee Mile	1.68
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Levee mile 1.68, looking at the vegetation on the waterside slope.

cathom\_s\_20110405\_124.jpg



Levee Mile Report Line	4
Start Levee Mile	1.68
End Levee Mile	1.68
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Levee mile 1.68, looking at the vegetation on the landside slope.

cathom\_s\_20110405\_125.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 0784 Plumas Lake**

Waterway			Bank	Unit Miles
Unit No. 02 Feather River			Left	13.64

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/17/2011 - 3/17/2011			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 02 Feather River				Left	13.64	03/17/2011 03/17/2011	Clay Thomas	

  

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	9.40	9.40	Earthen Levee	Encroachments	LS	CO	Buildings	39.003905 ° -121.578774 °	39.003905 ° -121.578774 °	1 Y
2	12.12	12.12	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	39.961941 ° -121.576607 °	39.961941 ° -121.576607 °	2 Y
3	12.12	12.12	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	39.961941 ° -121.576607 °	39.961941 ° -121.576607 °	3 Y

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	13.64	03/17/2011 03/17/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	9.40
End Levee Mile	9.40
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Levee mile 9.40, looking at a building that is encroaching on the levee toe.

cathom\_s\_20110405\_123.jpg



Levee Mile Report Line	2
Start Levee Mile	12.12
End Levee Mile	12.12
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Levee mile 12.12, looking at the vegetation on the waterside slopel.

cathom\_s\_20110405\_121.jpg



Levee Mile Report Line	3
Start Levee Mile	12.12
End Levee Mile	12.12
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Levee mile 12.12, looking at the vegetation on the landside slope.

cathom\_s\_20110405\_122.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 0784 Plumas Lake**

Waterway				Bank	Unit Miles
Unit No. 03 Bear River				Right	4.73
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	3/17/2011 - 4/20/2011				
DWR Inspector	Clay Thomas				
Accompanied By	Steve Fordice				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Bear River	Right	4.73	03/17/2011 04/20/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	4.71	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	38.943320 ° -121.572440 °	38.985390 ° -121.510770 °	5 Y
2	0.00	4.71	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	38.943320 ° -121.572440 °	38.985390 ° -121.510770 °	6 Y
3	2.44	3.20	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	38.970724 ° -121.547482 °	38.974683 ° -121.535296 °	2
4	2.44	3.20	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	38.970725 ° -121.547482 °	38.974683 ° -121.535296 °	1
5	2.82	2.82	Earthen Levee	Encroachments	CR PO		Equipment Inspector Comments: hwy 70 new bridge construction	38.974003 ° -121.541910 °	38.974003 ° -121.541910 °	4

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Bear River	Right	4.73	03/17/2011 04/20/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	4.71
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Levee mile 2.44, looking downstream at the vegetation on the waterside slope.

cathom\_s\_20110505\_154.jpg



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	4.71
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Levee mile 2.44, this photo is looking downstream at the vegetation on the landside slope.

cathom\_s\_20110505\_155.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 0784 Plumas Lake**

Waterway				Bank	Unit Miles
Unit No. 04 Interceptor Canal				Right	6.35
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	3/17/2011 - 3/17/2011				
DWR Inspector	Clay Thomas				
Accompanied By	Steve Fordice				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Interceptor Canal	Right	6.35	03/17/2011 03/17/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	5.86	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	38.974736 ° -121.535103 °	39.058587 ° -121.543129 °	2
2	0.00	5.86	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	38.974737 ° -121.535102 °	39.058586 ° -121.543130 °	1
3	4.31	4.43	Earthen Levee	Erosion / Bank Caving	CR	A	Note and monitor erosion site.	39.036594 ° -121.542377 °	39.038493 ° -121.542380 °	4 Y
4	5.56	5.56	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	39.054866 ° -121.542463 °	39.054866 ° -121.542461 °	5 Y
5	5.56	5.56	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	39.054866 ° -121.542463 °	39.054866 ° -121.542463 °	6 Y

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Interceptor Canal	Right	6.35	03/17/2011 03/17/2011	Clay Thomas

Levee Mile Report Line	3
Start Levee Mile	4.31
End Levee Mile	4.43
Location	Crown
Category	Earthen Levee
Item	Erosion / Bank Caving

Levee mile 4.31, looking at a crack near the landside shoulder with a temporary repair.

cathom\_s\_20110405\_118.jpg



Levee Mile Report Line	4
Start Levee Mile	5.56
End Levee Mile	5.56
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Levee mile 5.56, looking at the rock revetment on the waterside slope.

cathom\_s\_20110405\_120.jpg



Levee Mile Report Line	5
Start Levee Mile	5.56
End Levee Mile	5.56
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Levee mile 5.56, looking at the vegetation on the landside slope.

cathom\_s\_20110405\_119.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 0784 Plumas Lake**

Waterway				Bank	Unit Miles
Unit No. 05 Interceptor Canal				Left	4.20
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	4/20/2011 - 4/20/2011				
DWR Inspector	Clay Thomas				
Accompanied By	Steve Fordice RD 784				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 05 Interceptor Canal						Left	4.20	04/20/2011 04/20/2011	Clay Thomas	

  

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	3.87	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	38.974737 ° -121.532712 °	39.019481 ° -121.515068 °	1 Y
2	0.00	3.87	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	38.974737 ° -121.532711 °	39.019481 ° -121.515067 °	2 Y
3	1.08	1.72	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.989955 ° -121.535672 °	38.999068 ° -121.537462 °	10
4	2.10	3.06	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	39.004562 ° -121.538482 °	39.015593 ° -121.528533 °	9
5	3.88	4.20	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	39.019559 ° -121.514679 °	39.020574 ° -121.509016 °	11

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.20	04/20/2011 04/20/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	3.87
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Levee mile 3.87, looking downstream at the vegetation on the landside slope.	
cathom_s_20110505_156.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	3.87
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Levee mile 3.87, looking downstream at the vegetation on the waterside slope.	
cathom_s_20110505_157.jpg	

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 0784 Plumas Lake**

Waterway			Bank	Unit Miles
Unit No. 06 South Dry Creek			Right	1.50

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/20/2011 - 4/20/2011			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 06 South Dry Creek						Right	1.50	04/20/2011 04/20/2011	Clay Thomas

  

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.25	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	38.985550 ° -121.510470 °	38.987560 ° -121.506610 °	1 Y
2	0.00	0.25	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	38.985550 ° -121.510470 °	38.987560 ° -121.506610 °	2 Y

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 06 South Dry Creek	Right	1.50	04/20/2011 04/20/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.25
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Levee mile 0.00, looking upstream at the vegetation on the landside slope.	
cathom_s_20110505_159.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	0.25
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Levee mile 0.00, looking upstream at the vegetation on the waterside slope.	
cathom_s_20110505_158.jpg	

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 0784 Plumas Lake**

Waterway			Bank	Unit Miles
Unit No. 07 Yuba River			Left	3.91

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/17/2011 - 3/17/2011			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Yuba River						Left	3.91	03/17/2011 03/17/2011	Clay Thomas

  

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.02	3.90	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	39.134789 ° -121.551839 °	39.165479 ° -121.495652 °	1
2	0.02	3.90	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	39.134789 ° -121.551839 °	39.165479 ° -121.495652 °	2
3	1.68	1.68	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements.	39.144445 ° -121.524184 °	39.144445 ° -121.524184 °	6 Y
4	1.68	1.68	Earthen Levee	Vegetation	LS	A	Control annual grass and weeds on the levee slopes and easements.	39.144445 ° -121.524184 °	39.144445 ° -121.524184 °	7 Y
5	2.18	2.18	Earthen Levee	Encroachments	WS	CO	Buildings	39.149330 ° -121.518550 °	39.149330 ° -121.518550 °	4 Y
6	2.28	2.58	Supplemental	USACE Erosion Survey	WS	U	Inspector Comments: 2009: no berm, 1:1 slope, seepage, sands and silts, 0 ft/s [2009 SiteID:YUB_2-3_L]	39.153581 ° -121.513844 °	39.150442 ° -121.517481 °	5 Y

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Yuba River	Left	3.91	03/17/2011 03/17/2011	Clay Thomas

Levee Mile Report Line	3
Start Levee Mile	1.68
End Levee Mile	1.68
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Levee mile 1.68, looking at the vegetation on the waterside slope.

cathom\_s\_20110405\_126.jpg



Levee Mile Report Line	4
Start Levee Mile	1.68
End Levee Mile	1.68
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Levee mile 1.68, looking at the vegetation on the landside slope.

cathom\_s\_20110405\_127.jpg



Levee Mile Report Line	5
Start Levee Mile	2.18
End Levee Mile	2.18
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Water side buildings and equipment levee mile 2.18.

cathom\_s\_20110228\_076.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated

C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Yuba River	Left	3.91	03/17/2011 03/17/2011	Clay Thomas

Levee Mile Report Line	5
Start Levee Mile	2.18
End Levee Mile	2.18
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Water side buildings and equipment levee mile 2.18.	
cathom_s_20110228_077.jpg	



Levee Mile Report Line	6
Start Levee Mile	2.28
End Levee Mile	2.58
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
2009: no berm, 1:1 slope, seepage, sands and silts, 0 ft/s [2009 SiteID:YUB_2-3_L]	
cathom_s_20110228_078.JPG	

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 0784 Plumas Lake**

Waterway			Bank	Unit Miles
Unit No. 08 Three Rivers			Right	1.88
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)	Unit Not Inspected			
Date of Inspection	6/7/2011 - 6/7/2011			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 08 Three Rivers						Right	1.88	06/07/2011 06/07/2011	Clay Thomas

  

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.04	1.88	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.955523 ° -121.574250 °	38.970157 ° -121.547852 °	1 Y
2	0.04	1.88	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.955524 ° -121.574250 °	38.970157 ° -121.547852 °	2 Y

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 08 Three Rivers	Right	1.88	06/07/2011 06/07/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.04
End Levee Mile	1.88
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Levee mile 0.04, this photo is showing the vegetation on the landside slope.

cathom\_s\_20110607\_200.jpg



Levee Mile Report Line	2
Start Levee Mile	0.04
End Levee Mile	1.88
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Levee mile 0.04, this photo shows the vegetation on the waterside slope.

cathom\_s\_20110607\_201.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected/Rated

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2011 Levee Inspection Results**

**Reclamation District No. 0784 Plumas Lake**

Waterway			Bank	Unit Miles
Unit No. 09 Three Rivers Setback Levee			Left	5.73

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)	Unit Not Inspected			
Date of Inspection	6/7/2011 - 6/7/2011			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Suite 200  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 09 Feather River, TRLIA Setback Levee	Left	5.73	06/07/2011 06/07/2011	Clay Thomas

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.04	5.63	Earthen Levee	Vegetation	WS	W	Control annual grass and weeds on the levee slopes and easements.	39.089684 ° -121.584890 °	39.011181 ° -121.579795 °	2 Y
2	0.04	5.63	Earthen Levee	Vegetation	LS	W	Control annual grass and weeds on the levee slopes and easements.	39.089684 ° -121.584890 °	39.011180 ° -121.579795 °	1 Y

**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2011**

**Reclamation District No. 0784 Plumas Lake**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 09 Feather River, TRLIA Setback Levee	Left	5.73	06/07/2011 06/07/2011	Clay Thomas

Levee Mile Report Line	1
Start Levee Mile	0.04
End Levee Mile	5.63
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Levee mile 0.04, this photo is showing the vegetation on the waterside slope.

cathom\_s\_20110607\_199.jpg



Levee Mile Report Line	2
Start Levee Mile	0.04
End Levee Mile	5.63
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Levee mile 0.04, this photo is showing the vegetation on the landside slope.

cathom\_s\_20110607\_198.jpg



**\* Location**

LS : Landside  
WS : Waterside  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected/Rated  
C : Corrected  
W : Watch/Monitor